



# Standocryl VOC Xtreme Clear.

## Elección del endurecedor

Condiciones de Humedad Relativa y Temperatura:	10-20°C	20 - 30°C	> 30°C
Humedad Relativa <25%	Standox Xtreme Hardener fast	Standox Xtreme Hardener fast Standox Xtreme Hardener	Standox Xtreme Hardener
Humedad Relativa 25%-50%	Standox Xtreme Hardener fast Standox Xtreme Hardener	Standox Xtreme Hardener	Standox Xtreme Hardener slow
Humedad Relativa >50%	Standox Xtreme Hardener	Standox Xtreme Hardener Standox Xtreme Hardener slow	Standox Xtreme Hardener slow